



Contract No. 8127	Station NA	Mile/Line: I-90 WB	C/S
Staked by NA	Date	Work Started Date 6/3/2019	Work Completed Date 7/24/2019
Calculated by Colton Peyser	Date 7/24/2019	Checked by E. Knudson	Inspector Colton Peyser
		Date 8/14/2019	Date 7/24/19

## BI 579

Change Order 118 Flow Splitter

Contractor Properly Installed Flow Splitter handles on the following Structures:

- DR03-4 Paid 50% on Estimate 76. Pay Remaining 50%
- DR03-12A Paid 50% on Estimate 72. Pay Remaining 50%
- DR03-14 Paid 50% on Estimate 72. Pay Remaining 50%.
- DR04-4A Paid 50% on Estimate 76. Pay Remaining 50%.
- DR04-9 Paid 50% on Estimate 76. Pay Remaining 50%.

50% on 5 Structures listed above.

5 Structures x 50% = 2.5 each.

OK TO PAY 2.5

Item Num	Material Brand Name/Model Type	Manufacturer	Brand Name/Model Type	RAMS/QPL Ref. No.	Appr/Acc Code	Basis of Accept
579.01	Other	Atwood Fabricating	Flow Splitter	QPL-0332	2230	/
579.01	Other Expansion Bolts	ITW RedHead	Expansion Bolts	RAM-0321	7 2	/

Item Num	Item Description	Grp	Date Work Complete	Unit	Quantity	Ledger Entry No.	Posted By Init.	Posted By Date	Checked By Init.	Checked By Date	Est. No.
0579	CO 118-FLOW SPLITTER	1	8/5/2019	EAC H	2.5	7385	EK	08/14/19			93

### Attachments

File Attachment